

## Tree Removals: 2019 -1

	<p>364 Atterbury, Front Side Yard Under HPP Wires</p>	<p>4" Hemlock, 12" Spruce</p>	<p>Line and Streetlight Clearance</p>	<p>Remove</p>	<p>2019</p>
	<p>431 North Main, Backyard Near HPP Wires</p>	<p>23" Black Locust</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2019</p>
	<p>136 Elm, Back Yard Near HPP Wires</p>	<p>6", 12" Spruce</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2019</p>
	<p>18 Nantucket / 163 South Main, Back Yard Under HPP Wires</p>	<p>2 Dead Ash, 1 Cherry in Guy Wire</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2019</p>

## Tree Removals: 2019-2

	247 Cheshire, Front Tree Lawn	3 - 4" Maple	Dying	Remove	January 2019
	2433 Glen Echo, Front Tree Lawn	36" Poplar	Hazard	Remove	January 2019
	31 Great Oak, Front Tree Lawn	11" Pin Oak	Dying	Remove	January 2019
	7196 Granby, Hines Hill Tree Lawn	Seven Dead or Dying Spruce	Hazard to Wires and Roadway	Remove	January 2019